Office Memorandum . United states government

•				
то ;	Chief, Engineering Divisio	n	DATE: 14 October	1953
FROM :	Chief, Test & Evaluation S	ection		
SUBJECT:	Recording Equipment on Procurement from RD-XG-35		50X ²	
	1. Considerable difficulty has been encountered in getting the recording equipment mentioned above to perform satisfactorily in this Section. The prime reason is that a lot of distortion is encountered in recording from an SP-600JX receiver. 2. Several units have been tried and as of this date, no suitable recordings have been made. It is suspected that this may be due to overdriving of the recorder. However, there is no proof, and there is no method of reducing the gain to the recorder.			this
				y f,
	3. It was the understanding of the Chief. T. & E., that a representative of would be present and available to determine whether or not the proper procedure was being followed in the setting up of this equipment. 4. One set of equipment was delivered and assembled at and was found to work satisfactorily. However, it has not been possible to duplicate this operation in our shop.			50X ⁻
				50X1
	5. It would therefore seem advisable to contact the manufacturer of this equipment and request their advice or consultation.			
				50X1
	HHM/dd (14 October 1953)			
	Distribution: 1 - Courtesy 1 - Chrono 1 - C&ERB 1 - T&E Ref. No. 01435]
ORIGINAL CLEY <u>23</u> Decle Reywon Ext byno 6 yrs by	2610	M / 1	3 01 56 FYE 2 3 01 56 FYE 2 1 1 324 31 55 C	